

Figure 1 (ENGINE OFF, BOTH VALVES closed)




Figure 2 (ENGINE RUNNING WITH THROTTLES CLOSED - LIKE GOING DOWNHILL)




FIGURE 3

(ENGINE RUNNING WITH  
OPEN THROTTLE AND LITTLE  
MANIFOLD VACUUM -- LIKE  
GOING OFFHILL)